

# Canon EOS 1

## Viewfinder Information

The bright and easy-to-read viewfinder displays only necessary information at the bottom and the right side. The diagram here shows all the information for explanation only. All the information never actually appears simultaneously.

Correct exposure index

Exposure step indicator  
( - : 1 step, . : 1/3 step)

Overexposure  
(3 steps or more)

Exposure value indicator

Underexposure  
(3 steps or more)

Remaining frame counter  
(F: more than 9, 9-0)

Underexposure range

Overexposure range

Laser-matte screen

Manual exposure mark

AE lock indicator/AEB indicator

Shutter speed

Depth-of-field AE indicator (dEP 1, dEP 2)

Aperture value

Exposure compensation indicator

Flash charge completion indicator

AF in-focus indicator (Lights when AF completes. Blinks when AF is impossible.)

AF frame

Spot metering mark approx. 2.3% of the picture area

Partial metering mark approx. 5.8% of the picture area

